




2118-10

spindle lift knob is included






warning when over tolerance





- Display can rotate 320°, and display direction is changeable
- Reading in digital and analog
- Button function: tolerance Go and No-Go display, data preset, measuring direction change, max./min./TIR measurement, inch/metric conversion, absolute/incremental measurement
- Keep preset data and tolerance data in memory after restart
- CR2032 battery, automatic power off
- Data output
- Optional accessory: data output cable (code 7315-50M, 7302-40M, 7305-40M), backs (page 176~177), contact points (page 173~175)

display direction is changeable



Remark: To change above direction, 4 fixing screws on the back of display need to be removed first.

display can rotate 320°



Code	Range	Resolution	Accuracy	Hysteresis	Remark
2118-10 *	12.7mm/0.5"	0.01mm/0.0005"	20µm	10µm	flat back
2118-101*	12.7mm/0.5"	0.001mm/0.00005"	5µm	2µm	flat back

^{*}Supplied with manufacturer inspection certificate traceable to NIST USA