

End mills



1 tooth cut over centre



CZ Frézy válcové čelní | 1 břit přes střed

DE Schaftfräser | 1 Schneide über die Mitte

RU Фрезы концевые с цилиндрическим хвостовиком | с центрорежущим зубом



1104

1114



D k 10	d h 6	I1 1104	I1 1114	I2 1104	I2 1114	Z	110418	111418
2	6	51		7		3	.020	
2,5	6	52		8		3	.025	
3	6	52		8		3	.030	
4	6	55		11		3	.040	
4,5	6	55		11		3	.045	
5	6	57		13		3	.050	
6	6	57	68	13	24	3	.060	.060
7	10	66	80	16	30	3	.070	.070
8	10	69	88	19	38	3	.080	.080
9	10	69	88	19	38	3	.090	.090
10	10	72	95	22	45	3	.100	.100
11	12		102		45	3		.110
12	12	83	110	26	53	3	.120	.120
14	12	83	110	26	53	3	.140	.140
15	12	83	110	26	53	3	.150	.150
16	16	92	123	32	63	3	.160	.160
18	16	92	123	32	63	3	.180	.180
20	20	104	141	38	75	3	.200	.200
25	25	121	166	45	90	3	.250	.250
30	25	121	166	45	90	3	.300	.300

Cutting conditions | Řezné podmínky | Schnittbedingungen | Условия резания

		fz (mm/z)											
Material		Ap	Ae	Vc	Ø 3	Ø 6	Ø 8	Ø 10	Ø 12	Ø 16	Ø 18	Ø 20	Ø 25
P.1	≤ 600 N/mm²	1,5xD	0,1xD	45	0,006	0,015	0,021	0,028	0,034	0,044	0,051	0,057	0,071
N.2	≤ 600 N/mm²	1,5xD	0,1xD	160-300	0,0078	0,0195	0,0273	0,0364	0,0442	0,0572	0,0663	0,0741	0,092